

**BAUSCH[®]
& LOMB**

TELESCOPES


Harbormaster[™]

**Congratulations on
becoming the owner of the
Bausch & Lomb[®]
HARBORMASTER Telescope.**

**Following a few simple
precautions for care will
aid in the preservation of
this fine instrument.**



Harbormaster™



The Harbormaster Telescope

BAUSCH[®] & LOMB

TELESCOPES

First attach the legs to base using 3 leg bolts 26 and 3 leg nuts 5. Then line up parts 11, 22, 17, and 8 as shown.

Set cradle on top of base, and thread bolt into cradle. Bolt 11 should be secured tight. A 1/2 inch socket wrench is needed for this operation. A drop of adhesive on the thread of the screw 11 will prevent loosening.

Set cradle in horizontal position and lock. Set telescope in cradle with the threaded holes up and insert cradle screws 25. A drop of oil will assure smooth motion of the Telescope during use. Vertical motion movement is controlled by slightly loosening or tightening the lock nuts.

Congratulations on becoming the owner of the Bausch & Lomb HARBORMASTER Telescope. Following a few simple precautions for care will aid in the preservation of this fine instrument.

CLEANING AND CARE OF THE BRASS

Do not use polish or use abrasives on the brass parts. Simply wipe the moistened cloth and dry.

TRIPOD

The wooden legs can be waxed with furniture wax or polish with same care given to furniture.

LENSES

If ever necessary to clean, wipe using only a water-dampened soft cloth, free of abrasives of commercial cleaners that could scratch or etch the glass.

The **HARBORMASTER** Telescope is packed in four groups:

1. Telescope
2. Cradle
3. Base
4. legs

In addition, you will find the connecting hardware:

- 2 cradle screws (25)
- 3 leg bolts (26)
- 3 leg nuts (5)
- 1 center bolt (11)
- 1 washer (22)
- 1 spring (17)
- 1 spacer (8)

WARRANTY/REPAIR

TELESCOPE LIFETIME LIMITED WARRANTY

Your telescope is warranted to be free of defects in materials and workmanship for the lifetime of the original owner. The Lifetime Limited Warranty is an expression of our confidence in the materials and mechanical workmanship of our products and is your assurance of a lifetime of dependable service.

If your telescope contains electrical components the electronic components are warranted to be free of defects in materials and workmanship for one year after the date of purchase.

In the event of a defect under this warranty, we will, at our option, repair or replace the product, provided that you return the product postage prepaid. This warranty does not cover damages caused by misuse or improper handling, installation or maintenance of the product.

Any return made under this warranty must be accompanied by the items listed below:

- 1) A check in the amount of \$15.00 to cover the cost of handling
- 2) Name and address for product return
- 3) An explanation of the defect
- 4) Product should be well packed in a sturdy outside shipping carton to prevent damage in transit and return postage prepaid to the address listed below:

IN U.S.A. Send To:

Bushnell Performance Optics
8500 Marshall Drive
Lenexa, Kansas 66214

IN CANADA Send To:

Bushnell Performance Optics
25A East Pearce Street, Unit 1
Richmond Hill, Ontario L4B 2M9

For products purchased outside the United States and Canada please contact your local dealer for applicable warranty information. This warranty gives you specific legal rights. You may have other rights which vary from country to country.

©2001 Bushnell Performance Optics